

COLLEGE/UNIVERSITIES/SCHOOLS:

_____ Burnham House-UM	Ann Arbor	MI	Principal	1998	Building move & comprehensive rehabilitation, barrier free entrance
_____ Burton Tower-UM	Ann Arbor	MI	Principal	1998	Exterior restoration, barrier free entrance
_____ Buttrick Hall-Vanderbilt	Nashville	TN	Principal	2002	Exterior restoration, consultant to local firm
_____ Cranbrook Library & Gallery	Bloomfield Hills	MI	PM		Water infiltration & moisture study, report & recommendations
_____ Cravath Hall-Fisk University	Nashville	TN	Principal	2010	Water infiltration study and assessment report
_____ Detroit Observatory-UM	Ann Arbor	MI	PM	1995-8	HSR, comprehensive exterior & interior restoration
_____ Kingswood School-Cranbrook	Bloomfield Hills	MI	PM	1988, 2004	Interior treatments, new copper roof
_____ Lansing Carnegie Bldg-LCC	Lansing	MI	Principal	2006	Exterior restoration, terra cotta cornice
_____ Lane Hall-UM	Ann Arbor	MI	PM	1998	Exterior restoration, compatible addition, barrier free
_____ Martha Cook Dormitory-UM	Ann Arbor	MI	PM	2001	Barrier free entrance & elevator, interior assessment & report
_____ Science Center-EMU	Ypsilanti	MI	Principal	1998	Concept & programming study
_____ Sherzer Hall-EMU	Ypsilanti	MI	Principal	1988	Comprehensive restoration, fire-damage reconstruction

COMMERCIAL/OFFICE/ADAPTIVE USE:

_____ Argus Office Building	Ann Arbor	MI	PA	1986	Comprehensive rehabilitation, tax credit project
_____ Central Farmers Mkt. (HF)	Dearborn	MI	Principal	2009	Document to restore Central Farmers' Market at Greenfield Village
_____ Ford Rouge Plant Study	Dearborn	MI	Principal	1999	HSR, abbreviated and illustrated report
_____ Hecker-Smiley Law Offices	Detroit	MI	PA	1989	Tax credit rehabilitation, documents & oversight
_____ Ann Arbor Railroad/Old Post Off	Howell	MI	PM	1990	Comprehensive rehabilitation, exterior restoration
_____ Pere Marquette Depot	Bay City	MI	Principal	2002-5	Comprehensive rehabilitation, rebuilt tower & canopies
_____ Zingerman's Deli	Ann Arbor	MI	Principal	2007	Historic assessment & recommended approach to treatment

GOVERNMENT:

_____ Bay City City Hall	Bay City	MI	Principal	2006, 2011	Restored front doors, atrium glass, clay tile roof, & interior finishes
_____ Bay County Courthouse	Bay City	MI	Principal	1994	Building rehabilitation and adapted for courts & office use
_____ Idaho State Capitol	Boise	MI	PM	1994	Interior marble restoration, rotunda paint investigation
_____ Lucas County Courthouse	Toledo	MI	Principal	2005	Exterior assessment of masonry, dome, windows, doors, & lighting
_____ Marshall County Courthouse	Lewisburg	TN	Principal	2008, 2013	Conditions assessment, masonry restoration, window repairs
_____ Michigan State Capital	Lansing	MI	PA/PM/Pr	1989-2014	Exterior masonry & dome restoration, copper roof, rebuilt stone steps
_____ Milwaukee City Hall	Milwaukee	WI	Principal	2003-5	HSR, NHL, HABS update, peer review of masonry restoration
_____ Washtenaw County Old Post Off	Ann Arbor	MI	Principal	2001	Exterior masonry restoration, new storm windows
_____ Wayne County Courthouse	Detroit	MI	PM/Princ	1988, 2014	Comprehensive restoration, revisit & assessment of conditions

HISTORIC HOUSES:

_____ Adams/Franklin House	Deadwood	SD	PM	1997	HSR, comprehensive restoration, barrier free & visitor's center add'ns.
_____ Alden Dow Home & Studio	Midland	MI	Principal	1998	Comprehensive investigation, measured drawings
_____ Cappon House	Holland	MI	PM	1996	Comprehensive study & restoration, building & site
_____ Dougherty House	Mission Penin	MI	Principal	2009	HSR, interpretive reuse plan for the house and outbuildings
_____ Fairlawn	Superior	WI	PM	1996	Comprehensive restoration, exterior & interior
_____ Fair Lane/Henry Ford Estate	Dearborn	MI	Principal	2001, 2013	Water infiltration study
_____ Freer House-Wayne State	Detroit	MI	PM	1994, 2009	Comprehensive rehabilitation, new roof, barrier free entrance

_____ Fallingwater	Bear Run	PA	PA	1989	Research of historic paint coatings; color research for work by others
_____ Miller House	Springfield	IL	Principal	2003	HSR, comprehensive investigation & report
_____ Museum on Main Street	Ann Arbor	MI	Principal	1989, 2002	Building moved & restored, paint color assessment
_____ Tuomy House	Ann Arbor	MI	PM	1989	Comprehensive rehabilitation, barrier free entrance
_____ Villa Louis	Prairie du Chien	WI	PM	1995	Comprehensive study & restoration, replicated historic finishes

HISTORIC SITES:

_____ Crossroads Village	Flint	MI	PM	1986	Restoration of several structures within the historic village
_____ Fayette Historic Townsite	Garden Penin	MI	PM	1995	CLR, assessment & recommendations for each structure
_____ George Rogers Clark Memorial	Vincennes	IN	Principal	2014	Conditions assessment & recommendations report
_____ Lincoln Boyhood National Mem.	Lincoln City	IN	Principal	1997	HSR, evaluation of several options for reuse & interpretation
_____ Nankin Mills Interpretive Center	Westland	MI	PM	1998	Comprehensive restoration & expansion of historic mill building
_____ Old Courthouse, JNEM	St. Louis	MO	Principal	1995-2012	Cornice & water infiltration studies; copper roof, cornice restoration

HOTEL:

_____ Dearborn Inn	Dearborn	MI	PM	1992	Restoration of detached cottages, tax credit rehab of hotel windows
--------------------	----------	----	----	------	---

LIBRARIES:

_____ Hall Fowler Memorial Library	Ionia	MI	Principal	2000	Conditions assessment & recommendations for reuse
_____ Howell Carnegie Library	Howell	MI	PM/Princ	1988, 2012	Exterior restoration, interior rehabilitation, reuse studies
_____ Jackson District Library	Jackson	MI	Principal	2002	Conditions assessment & recommendations for reuse
_____ Kalamazoo Ladies' Library	Kalamazoo	MI	PM	1992	Exterior restoration, copper built-in gutters & slate roof
_____ McGregor Library	Highland Park	MI	Principal	2000	Conditions assessment & recommendations for reuse

LIGHTHOUSES:

_____ Fort Gratiot Lighthouse	Port Huron	MI	Principal	2006, 2010	HSR for the entire site, restoration of light and fog signal buildings
_____ South Channel Range Lights	Harsen's Island	MI	Principal	2004, 2013	Masonry restoration, seawall installation, secured against vandals

MASTER PLANNING (SITE):

_____ Campus Master Plan-EMU	Ypsilanti	MI	Principal	2003	Concept design & recommendations for all three EMU campuses
_____ Cultural Resources Plan-UW	Madison	WI	Principal	2003	Comprehensive landscape research & report, funded by The Getty
_____ Henry Ford Estate-UM	Dearborn	MI	Principal	2001-3	Concept plan for historic western part of UM-Dearborn campus
_____ Huron, Fifth, & Division	Ann Arbor	MI	Principal	2004	Urban design study for three major through-traffic roadways

PERFORMING ARTS:

_____ City Opera House	Traverse City	MI	Principal	2001, 2014	Construction oversight for phased implementation, new dressing rooms
_____ Greek Theatre & Actors' Court	Bloomfield Hills	MI	PA	1988	Site & landscape restoration, masonry & stucco repairs
_____ Hill Auditorium-UM	Ann Arbor	MI	PM	2001-3	Exterior restoration, terra cotta cornice
_____ Michigan Theater	Ann Arbor	MI	Principal	1986, 2012	Construction oversight for initial restoration, donor panels
_____ Municipal Auditorium-KC	Kansas City	KS	Principal	2005	Exterior masonry assessment & recommendations
_____ Pease Auditorium-EMU	Ypsilanti	MI	Principal	1996, 2007	Interior & exterior restoration, terra cotta cornice reconstruction
_____ Ramsdell Theatre	Manistee	MI	PM	1993	Comprehensive restoration of auditorium, barrier free entrance
_____ Strand Theatre	Pontiac	MI	PM	1988	Façade restoration, cast-stone, decorative sheet metal

_____Wealthy Theatre	Grand Rapids	MI	PM	1989-1994	Comprehensive restoration, barrier free entrance
_____Whiting Auditorium	Flint	MI	PM	1998	Comprehensive rehabilitation, new seating

RELIGIOUS BUILDINGS:

_____Bethlehem United Church	Ann Arbor	MI	PM	1988-2005	Exterior restoration, organ expansion & altar redesign, reuse studies
_____Cathedral of St. Andrew	Grand Rapids	MI	Principal	1998-2000	Comprehensive exterior & interior restoration, site design, new organ
_____Christian Science-Boston	Boston	MI	Principal	1987-2014	Exterior restoration, ongoing consulting, lighting, hardware, paint colors
_____Christ Church-Detroit	Detroit	MI	PM	1994-2005	Exterior masonry and art glass restoration, reuse studies
_____First Congregational-Detroit	Detroit	MI	Principal	1997	Restoration of exterior red sandstone masonry, rebuilt front steps
_____Dixboro Church	Dixboro	MI	Principal	2006	Comprehensive exterior & interior restoration, reconstructed tower
_____First Congregational of AA	Ann Arbor	MI	Principal	2004	Exterior restoration & new slate roof, decorative stenciling exposed
_____First Presbyterian of AA	Ann Arbor	MI	Principal	2002	Exterior masonry restoration, rebuilt front & side steps
_____Guardian Angels Cath Church	Manistee	MI	Principal	2007	Exterior masonry assessment & recommendations report
_____Jefferson Ave Presby Church	Detroit	MI	PM	1986	Exterior masonry & art glass restoration, new roof
_____Kirk in the Hills	Bloomfield Hills	MI	PM	1993-2001	Restored bell tower, masonry restoration, reuse studies
_____St. Andrew's Episcopal Church	Ann Arbor	MI	Principal	1991-2007	Comprehensive exterior & interior restoration, slate roof, organ studies
_____St. James Episcopal Chapel	Grosse Ile	MI	Principal	2001	Conditions assessment & recommendations report
_____Temple Israel	Bay City	MI	Principal	2007	Conditions assessment & recommendations report

VISUAL ARTS:

_____Parthenon Museum	Nashville	TN	Principal	1993-2004	Exterior restoration of decorative J.J. Earley concrete, plaster soffit
_____Crooked Tree Arts Center	Petoskey	MI	Principal	2000	Comprehensive rehabilitation plus addition, barrier free entrance
_____Frist Center for Visual Arts	Nashville	TN	Principal	1998	Exterior restoration treatments, interior paint colors
_____Saginaw Art Museum	Saginaw	MI	Principal	1997	Exterior restoration, new roof, rehabilitated windows

MATERIAL CONSERVATION:

_____Bay Furnace	Christmas	MI	Principal	1993	Reconstruction of stone & timber pig iron furnace & surrounding site
_____Campus Martius Monument	Detroit	MI	Principal	2002	Move, reconstruct, & restore granite civil war monument
_____Culpeper Nat'l Cemetery	Culpepper	VA	Principal	2010	Brick wall restoration; high-definition laser scan documentation
_____Cypress Hill Nat'l Cemetery	Brooklyn	NY	Principal	2010	Historic cast iron fence & gate restoration
_____Bicentennial Park	Franklin	TN	Principal	2006	Cemetery assessment of City & Rest Haven Cemeteries
_____Hurlbut Memorial Gateway	Detroit	MI	Principal	2008	Sandstone monument & gate reconstruction; high-def laser scan
_____Michigan Central Station	Detroit	MI	Principal	2011	Materials assessment & paint analysis
_____Veterans' Memorials	various sites, east US		Principal	2011	Historic monuments assessment & conservation